



X-TYPE

DATE 01/04

XT307-03

SERVICE

TECHNICAL BULLETIN

Scraping Noise –
1600 RPM, 1800 - 2500 RPM –
Install Modified Flexplate

MODEL 2002 MY-ON
X-TYPE
VIN C00001-ON

Issue:

Some X-TYPE vehicles may exhibit a scraping noise from the automatic transmission at approximately 1600 RPM, 1800 to 2500 RPM and at 2500 RPM when driving.

A modified flexplate is available to resolve this issue.

Action:

In case of a verified customer complaint of the above condition, install a new modified engine flexplate (see Workshop Manual, JTIS CD ROM, section: 303-01, SRO 44.20.01), noting the following:

Note: In the Transaxle installation step 13 gives a torque figure of 48 Nm. This should be **80** Nm.

Note: In the Transaxle installation procedure step 42 the reference to 'right-hand half shaft' should read '**left-hand drive half shaft**'.

Parts Information:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Engine flexplate	C2S 36487	1

Warranty Information:

Description	SRO	Time	Causal Part Number
Install engine flexplate	12.53.13	8.9 hrs.	C2S 36487

NOTE: The information in Technical Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers." Do not assume that a condition described affects your car. Contact a Jaguar retailer to determine whether the Bulletin applies to your vehicle.

